

U.S. DEPARTMENT OF LABOR
Occupational Safety and Health Administration

Form Approved
OMB No. 44-R1387

MATERIAL SAFETY DATA SHEET

Required under USDL Safety and Health Regulations for Ship Repairing,
Shipbuilding, and Shipbreaking (29 CFR 1915, 1916, 1917)

9/86

SECTION I

MANUFACTURER'S NAME The Herbert Burnishine Products division of Stanley Co.		EMERGENCY TELEPHONE NO. 312-583-1810
ADDRESS (Number, Street, City, State, and ZIP Code) 8140 N. Ridgeway Avenue, Skokie, Illinois 60076		
CHEMICAL NAME AND SYNONYMS Mixture - untested		TRADE NAME AND SYNONYMS Gestetner Putz Pomade Liquid Roller Cleaner
CHEMICAL FAMILY Mixture	FORMULA Liquid	

SECTION II - HAZARDOUS INGREDIENTS

PAINTS, PRESERVATIVES, & SOLVENTS	%	TLV (Units)	ALLOYS AND METALLIC COATINGS	%	TLV (Units)
PIGMENTS N/A			BASE METAL N/A		
CATALYST N/A			ALLOYS N/A		
VEHICLE N/A			METALLIC COATINGS N/A		
SOLVENTS N/A			FILLER METAL PLUS COATING OR CORE FLUX N/A		
ADDITIVES N/A			OTHERS N/A		
OTHERS N/A					
HAZARDOUS MIXTURES OF OTHER LIQUIDS, SOLIDS, OR GASES				%	TLV (Units)
Kerosene				5.5	500 ppm

SECTION III - PHYSICAL DATA

BOILING POINT (°F)	N/A	SPECIFIC GRAVITY (H ₂ O=1)	1.2423
VAPOR PRESSURE (mm Hg.)	N/A	PERCENT. VOLATILE BY VOLUME (%)	3.67
VAPOR DENSITY (AIR=1)	N/A	EVAPORATION RATE (_____ =1)	N/A
SOLUBILITY IN WATER	Insoluble		
APPEARANCE AND ODOR	Reddish heavy liquid		

SECTION IV - FIRE AND EXPLOSION HAZARD DATA

FLASH POINT (Method used) over 200°F (tag open cup)	FLAMMABLE LIMITS	LeI	UeI
EXTINGUISHING MEDIA Form, carbon dioxide, or dry chemical			
SPECIAL FIRE FIGHTING PROCEDURES none			
UNUSUAL FIRE AND EXPLOSION HAZARDS none			

SECTION V - HEALTH HAZARD DATA

THRESHOLD LIMIT VALUE

not determined

EFFECTS OF OVEREXPOSURE

not determined

EMERGENCY AND FIRST AID PROCEDURES

Remove from skin with soap and water. Eye Contact: Flush with plenty of water. Ingestion: Do not induce vomiting. Get immediate medical attention.

SECTION VI - REACTIVITY DATA

STABILITY

UNSTABLE

CONDITIONS TO AVOID

high heat

STABLE

X

INCOMPATIBILITY (Materials to avoid)

HAZARDOUS DECOMPOSITION PRODUCTS

HAZARDOUS
POLYMERIZATION

MAY OCCUR

CONDITIONS TO AVOID

WILL NOT OCCUR

X

SECTION VII - SPILL OR LEAK PROCEDURES

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED

Product is a viscous liquid at room temperature. If spilled, scoop up and wipe surface dry and wash with detergent and water.

WASTE DISPOSAL METHOD

Use local refuse or garbage disposal company.

SECTION VIII - SPECIAL PROTECTION INFORMATION

RESPIRATORY PROTECTION (Specify type)

none

VENTILATION

LOCAL EXHAUST

SPECIAL

MECHANICAL (General)

OTHER

none

PROTECTIVE GLOVES

none

EYE PROTECTION

Keep away from eyes.

OTHER PROTECTIVE EQUIPMENT

none

SECTION IX - SPECIAL PRECAUTIONS

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING

Store away from excessive heat and open flames.

OTHER PRECAUTIONS

none